
SITE PRESENTATION

UPPER LAKE

WOOD PROCESSING CAMPUS

View of Parcel and Location of Equipment





Rebuilt Encroachment Access Driveway Entrance See Detail of Asphalt


Leased Area

Rocked Access Corridor

Existing Farm Access Driveway


chance with average depth less than one foot or with drainage areas of less than one square mile


Clover Creek Left Bank (not tied into high ground)



View of Parcel and Potential Flood Area if Levee Breaks with Location of Project

Project is Located North of the High-Water Line



















Looking South at Location of Equipment



Looking North from Location of Equipment

