
SITE PRESENTATION

UPPER LAKE

WOOD PROCESSING CAMPUS


View of Parcel and Location of Equipment






Clover Creek Left Bank (not tied into high ground)






View of Parcel and Potential Flood Area if Levee Breaks with Location of Project

Project is Located North of the High-Water Line






Looking South from Location of Equipment








Looking South at Location of Equipment




Looking North from Location of Equipment











PROCESS COMPETED - BIOCHAR PRODUCED -